

Inspection Photos

8/17/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 327240

Inspection Doc. Number: 675103862

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken north of the battery facility, south of the well. Inspection doc. #682502147 required operator to remove riser. Photo shows riser still remains.