

Inspection Photos

8/17/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 318670

Inspection Doc. Number: 675103864

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 318670



Photo 1: Photo taken from the east end of the location, facing west. Inspection Doc. # 682502155 required operator to remove risers from the location. Photo shows pipe risers still remain.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 318670




Photo 2: Photo taken from the location. Photo shows one of the two risers still remaining on the location.



Photo 3: Photo taken from the location. Photo shows one of the two risers still remaining on the location.