

Inspection Photos

8/17/2017

Operator: EDDY OIL COMPANY - 26420

Location ID: 322675

Inspection Doc. Number: 675103868

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the battery location, facing south. Inspection doc. # 682502199 required operator to remove riser at the battery facility in accordance to the 2017 Flowline and Pipeline NTO, and per reclamation ruled. Photo shows riser remains on location.