

# Inspection Photos

8/17/2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP  
- 47120

Location ID: 318590

Inspection Doc. Number: 675103870  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 318590



**Photo 1:** Photo taken from the location, facing west. Photo shows meter sheds have been removed per CA's from inspection doc. #682502184



## Inspection Photos

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 318590



**Photo 2:** Photo taken from the east end of the location. Inspection doc. #682502184 required operator to manage weeds. Canada thistle remains evident throughout location. This is a Colorado State listed noxious weed and needs to be removed.



**Photo 3:** Photo taken from the central area of the location. Inspection doc. #682502184 required operator to manage weeds. Canada thistle remains evident throughout location. Photo shows thistle rosettes. This is a Colorado State listed noxious weed and needs to be removed.