

Inspection Photos

8/17/2017

Operator: PDC ENERGY INC - 69175

Location ID: 322636

Inspection Doc. Number: 675103872

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the battery location, facing west. Photo shows risers have been removed per CA.



Photo 2: Photo taken from the battery location. Inspection doc. #682502204 required operator to repair subsidence. Photo shows subsidence remains and appear to have degraded further. This needs to be repaired. 6 foot measuring stick for reference.



Photo 3: Photo taken from the battery location. Inspection doc. #682502204 required operator to repair subsidence. Photo shows subsidence remains and appear to have degraded further. This needs to be repaired. 6 foot measuring stick for reference.



Photo 4: Photo taken from the access road, facing north towards the well. Photo shows additional reclamation activities per doc. #682502204 does not appear to have been conducted.