

Inspection Photos
Location Name: Buzzard Creek Unit 15 O
Location ID: 334554



Photo 1. Hoses not stored in containment.




Photo 2. Multiple signs at one wellhead.

Inspection Photos
Location Name: Buzzard Creek Unit 15 O
Location ID: 334554



Photo 3. Poly pipe stored near entrance.



Photo 4. Condensate tanks labeled OUT OF SERVICE.