

# Inspection Photos

8/17/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 331152

Inspection Doc. Number: 675103888

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 331152



**Photo 1:** Photo taken from the battery location. Photo shows equipment has not been removed per CA's



**Photo 2:** Photo taken from the south end of the battery location. Photo shows reclamation has not been conducted.