

Inspection Photos
Location Name: Bucklen 12-31
API: 05-123-13590



Wellhead sign looking north



Wellhead looking north

Inspection Photos
Location Name: Bucklen 12-31
API: 05-123-13590



Wellhead looking west



Battery looking northeast from southwest edge of location

Inspection Photos
Location Name: Bucklen 12-31
API: 05-123-13590



South side of separator looking north



Tank battery sign looking north at tank

Inspection Photos
Location Name: Bucklen 12-31
API: 05-123-13590



Unused/unmarked 2" riser southwest side of crude tank



Animal burrow inside of tank berm northeast side

Inspection Photos
Location Name: Bucklen 12-31
API: 05-123-13590



Tank battery looking southwest

