

Photo#1:
Overview of Location from entry to South East.



August 8, 2017

Photo#2:

View of base of Pit slope populated with Thistle.

Photo#3:



August 8, 2017

Photo#3:

Dense Knapweed growth surrounding Guy Anchor..



August 8, 2017

Photo#4:

Access road has dense Knapweed Growth.



August 8, 2017