

Inspection Photos
Location Name: Swanson 28-21
API: 05-123-19250




Wellhead sign looking south



Wellhead looking south

Inspection Photos
Location Name: Swanson 28-21
API: 05-123-19250



Wellhead looking north



Access road looking south from county road. Well is in active crops, 2 track to wellhead

Inspection Photos
Location Name: Swanson 28-21
API: 05-123-19250



Tank battery sign looking east



Unused equipment/trash southwest corner of tank berm

Inspection Photos
Location Name: Swanson 28-21
API: 05-123-19250



Water vault looking southeast. No placard or capacity posted



Hole inside of tank berm northeast of crude tank. Measuring approx. 10" long, 7" wide, 10" deep.

Inspection Photos
Location Name: Swanson 28-21
API: 05-123-19250



Battery looking northeast from southwest edge of location



Battery looking south from ECDs

Inspection Photos
Location Name: Swanson 28-21
API: 05-123-19250



Well sign from county road headed south into well