

**Photo#1:**

View North, up Access Road going into Location.



August 8, 2017

Photo#2:

Looking out of Location along Access Road to South.



August 8, 2017



### Photo#3:


View over Location Center to South showing vigorous vegetation. Arrow indicates Access Road.



August 8, 2017

#### Photo#4:

Abandoned Riser at position N 40.76706 W 107.84252. Insert of Pressure gauge. Arrow indicates Access Road



August 8, 2017