

Photo#1:
View North over Location Center



Photo#2:
View South over Location Center



August 11, 2017

Photo#3:
View East over Location Center



Photo#4:
View West over Location Center



August 11, 2017

Photo#5:

Close up view of Vegetation on Site



Photo6:

View up Access Road, exiting Location to SE



August 11, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Utah Gas OP PA DA Powell API#103-11919 & 103-11921