

# Inspection Photos

8/22/2017

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 323581

Inspection Doc. Number: 675103897

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: EXTRACTION OIL & GAS INC - 10459  
Location ID: 323581



**Photo 1:** Photo taken from the center of the location, facing northeast. Photo shows the gully formations on the north half of the location have been repaired. However, no BMPs have been installed to mitigate future stormwater degradation concerns.



**Photo 2:** Photo taken from the center of the location, facing southwest. Photo shows the gully formations on the north half of the location have been repaired. However, no BMPs have been installed to mitigate future stormwater degradation concerns.

Inspection Photos  
Operator: EXTRACTION OIL & GAS INC - 10459  
Location ID: 323581



**Photo 3:** Photo taken from the south central area of the location, facing east. Photo shows the gully formations are beginning to form again on the southern end of the location. No BMPs have been installed to mitigate stormwater degradation concerns



**Photo 4:** Photo taken from the ditch that runs North/South on the west end of the location, facing east. It is unclear if ditch had been repaired since previous inspection; stormwater degradation remains evident and sediment laden storm water discharge from the location is being deposited into the irrigation ditch.





**Photo 5:** Photo taken from the ditch that runs North/South on the west end of the location, facing north. It is unclear if ditch had been repaired since previous inspection; stormwater degradation is remains evident and sediment laden storm water discharge from the location is being deposited into the irrigation ditch.