

Inspection Photos

8/22/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 323695

Inspection Doc. Number: 675103905

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323695



Photo 1: Photo taken from the northeast end of the battery location, facing south. Photo shows no reclamation activities have been conducted on the battery location.



Photo 2: Photo taken from the northeast end of the battery location, facing southwest. Photo shows no reclamation activities have been conducted on the battery location.