

Tidal Wave Energy
Dolan Ranches 13-27 Photo Log
August 23, 2017 COGCC Site Inspection



Crude oil leak at transfer pump



Pit #2 looking east



Pit #2 looking southeast



Pit #1 looking west



Pit #3 looking northeast



Pit #3 looking southwest



Skim Tank between pit # and pit #2



Hillman Spring stock tank