

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/17/2017

Submitted Date:

08/18/2017

Document Number:

689400127**FIELD INSPECTION FORM**
 Loc ID 334443 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Energy, Laramie		cogccnotifications@laramie-energy.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285899	WELL	PR	06/29/2007	GW	077-09117	VEGA UNIT 34-431	PR
286493	WELL	PR	08/24/2007	GW	077-09134	VEGA UNIT 34-421	PR
286494	WELL	PR	05/03/2008	GW	077-09133	VEGA UNIT 34-321	PR
286495	WELL	PR	07/08/2007	GW	077-09132	VEGA UNIT 34-414	PR
286496	WELL	PR	08/09/2007	GW	077-09131	VEGA UNIT 34-411	PR
286497	WELL	PR	04/16/2008	GW	077-09130	VEGA UNIT 34-311	PR
286498	WELL	PR	08/24/2007	GW	077-09129	VEGA UNIT 34-314	PR
286499	WELL	PR	09/28/2009	GW	077-09128	VEGA UNIT 34-324	PR
286528	WELL	PR	07/05/2007	GW	077-09135	VEGA UNIT 34-424	PR
286529	WELL	PR	01/09/2008	GW	077-09136	VEGA UNIT 34-331	PR
293460	WELL	PR	11/14/2007	GW	077-09452	VEGA FEDERAL 34-224	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 800-891-6191

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked riser @ 39.23655/-107.748681		
Corrective Action:	Comply with Rule 603.f .	Date:	09/18/2017

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	2	400 BBLS	STEEL AST		,		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	2	400 BBLS	HEATED STEEL AST		,		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	
<u>Venting:</u>							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities				
Facility ID: <u>285899</u>	Type: <u>WELL</u>	API Number: <u>077-09117</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>286493</u>	Type: <u>WELL</u>	API Number: <u>077-09134</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>286494</u>	Type: <u>WELL</u>	API Number: <u>077-09133</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>286495</u>	Type: <u>WELL</u>	API Number: <u>077-09132</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>286496</u>	Type: <u>WELL</u>	API Number: <u>077-09131</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>286497</u>	Type: <u>WELL</u>	API Number: <u>077-09130</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>286498</u>	Type: <u>WELL</u>	API Number: <u>077-09129</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>286499</u>	Type: <u>WELL</u>	API Number: <u>077-09128</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>286528</u>	Type: <u>WELL</u>	API Number: <u>077-09135</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>286529</u>	Type: <u>WELL</u>	API Number: <u>077-09136</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293460</u>	Type: <u>WELL</u>	API Number: <u>077-09452</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Ditches	Pass	Gravel	Pass			
Compaction	Pass	Check Dams	Pass			
Berms	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401381119	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4232189
689400138	Vega Unit Pad 334443	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4232179