

Photo#1:
Overview of Location to NW.



August 18, 2017

Photo#2:
Sediment trap area; under construction?



August 18, 2017

Photo#3:
Downslope from Sediment trap area.



August 18, 2017


Photo#4:

Photo#5:

North Side of Containment Area

View inside secondary containment; residual SW.

View outside containment to where SW is seeping



August 18, 2017