

Inspection Photos
Location Name: Marie Gerhardt B 5
API: 05-123-08916



Photo from prior inspection for comparison



Photo from operator



Inspection Photos
Location Name: Marie Gerhardt B 5
API: 05-123-08916



Photo from prior inspection for comparison



Photo 1: Riser marked after contact with operator