

Location			
Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to meter shed		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Stencil on water tank		
Corrective Action:	Add NFPA label. Install sign to comply with Rule 210.b.		Date: 09/18/2017
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds have been maintained since previous inspection. Form 42# 401366970		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Wire fence around wellhead, water tank and meter shed		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 252360 Type: WELL API Number: 125-06233 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [Access has been repaired since previous inspection. Form 42# 401366970](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT