

Inspection Photos
Location Name: Moonshine 36-11-65
API: 05-123-31800



Photo 1. Capacity installed Weeds Cut



Photo 2. Emergency Phone # Installed

Inspection Photos
Location Name: Moonshine 36-11-65
API: 05-123-31800



Photo 1. Wellhead containment repaired and cleaned up



Photo 2. Dead bird removed from heater treater burner assembly