

Inspection Photos
Location Name: Green #1-7 Facility
Facility ID # 423291



Photo 1. Sign



Photo 2. Containment device full of liquid and open

Inspection Photos
Location Name: Green #1-7 Facility
Facility ID # 423291



Photo 1. Containment equipment broken can allow wildlife intrusion