

Inspection Photos
Location Name: Grassy Creek Coal Co 2
API: 05-057-06351



Photo 1. Overview of location taken at the entrance facing northwest. Stained soil from exhaust visible.




Photo 2. Stained soil at wellhead.