

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401391165  
Date Received:  
08/30/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960  
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC  
Address: 410 17TH STREET SUITE #1400  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Brian Dodek</u>	<u>7202256653</u>	<u>bdodek@bonanzacrk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 684904069  
Inspection Date: 08/18/2017 FIR Submit Date: 08/18/2017 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Company Number: 8960  
Address: 410 17TH STREET SUITE #1400  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 331350

Location Name: Peterson Number: 14-28 Pad County: WELD  
Qtrqtr: SWS Sec: 28 Twp: 5N Range: 63W Meridian: 6  
Latitude: 40.365440 Longitude: -104.448360

FACILITY - API Number: 05-123-00 Facility ID: 430054

Facility Name: North Platte Number: J-F-28HZ  
Qtrqtr: SWS Sec: 28 Twp: 5N Range: 63W Meridian: 6  
Latitude: 40.365440 Longitude: -104.448360

CORRECTIVE ACTIONS:

1 CA# 93195

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 09/18/2017

Response: CA COMPLETED

Date of Completion: 08/30/2017

The compressor skid was drained and a hotsy was called out to spray the unit down. All of the stained and

Operator Comment: impacted gravel surrounding the skid was removed. All valves, pipes, and fittings were secured.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 93196

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 09/18/2017

Response: CA COMPLETED

Date of Completion: 08/30/2017

Operator Comment: The impacted gravel around the production tank load out was removed and all valves, pipes, and fittings were secured.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brian Dodek

Signed: \_\_\_\_\_

Title: Environmental Manager

Date: 8/30/2017 6:00:56 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files