



Photo 1: View of the project area from the southeastern corner facing center.



Photo 2: View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*) and dropseed (*Sporobolus* sp.). Musk thistles appear to be treated.



Photo 3: View of the eastern portion of the project area from the southeastern corner of the well pad facing northward.



Photo 4: View of pipes and debris in the western portion of the project area.