

Photo#1:

View North over Location Center
Arrow indicates Area not revegetated.



Photo#2:

View South over Location Center



August 23, 2017

Photo#3:

Close up of Land Farm area that has not revegetated, indicated by arrow in Photo#1



August 23, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Farleigh Oil PA Silver Spur API#057-06462

Photo#4:
View East over Location Center



Photo#5:
View West over Location Center



August 23, 2017

Photo#6:

Subsidence area at GPS Position N 40.69344 W-106.50381



August 23, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Farleigh Oil PA Silver Spur API#057-06462

Photo#7:

Close up views of Subsidence at GPS Position N 40.69344 W-106.50381

Photo#8:



August 23, 2017

Photo#9:

Canada thistle is established in vegetated areas of Location.



August 23, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Farleigh Oil PA Silver Spur API#057-06462