

Photo#1:

Looking From Location Entrance to South West.



August 24, 2017

Photo#2:

View of Pit area to North West.



Photo#3:

View of Pit area to south East.



August 24, 2017

Photo#4:
Canada thistle growing on Fill Slope.



August 24, 2017

Photo#5:
Canada thistle growing on Location.



August 24, 2017

Photo#6:

Small amount of Debris has been left on Location.

Photo#7:



August 24, 2017

Photo#8:
Trash dumped on Location.



August 24, 2017

Photo#9:

Access Road has not been Reclaimed.



August 24, 2017