

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401395572

Date Received:

09/06/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Reddy

970-515-1292

luke.reddy@anadarko.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680704319

Inspection Date: 08/01/2017

FIR Submit Date: 08/01/2017

FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 319331

Location Name: MARKHAM-64N68W Number: 15SWNW County: WELD

Qtrqr: SWN Sec: 15 Twp: 4N Range: 68W Meridian: 6
W

Latitude: 40.316213 Longitude: -104.995324

FACILITY - API Number: 05-123- -00 Facility ID: 243286

Facility Name: MARKHAM Number: 1

Qtrqr: SWN Sec: 15 Twp: 4N Range: 68W Meridian: 6
W

Latitude: 40.316213 Longitude: -104.995324

CORRECTIVE ACTIONS:

1 CA# 89195

Corrective Action: Install sign to comply with Rule 210.d.

Date: 10/02/2017

Response: CA COMPLETED

Date of Completion: 09/06/2017

Operator
Comment:

Tank had recently been repainted and was labeled after the paint dried.

COGCC Decision: _____

COGCC
Representative:

2 CA# 89196

Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date: 10/02/2017

Response: CA COMPLETED

Date of Completion: 09/06/2017

Operator
Comment:

PVC pipe inside of berm is used to transfer heat to equipment in cold weather.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: PVC pipe inside of berm is used to transfer heat to equipment in cold weather.
Tank had recently been repainted and was labeled after the paint dried.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Luke Reddy

Signed: _____

Title: Regulatory Specialist

Date: 9/6/2017 8:30:26 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

--	--

Total Attach: 0 Files