

- Day-V-Ranch 34-1/2 35 1
- 05-067-07468

- Day-V-Ranch 34-1/2 35 1
- 05-067-07468



Photo 1: Previous Inspection wellhead sign.

Photo 2: Wellhead sign.

- Day-V-Ranch 34-1/2 35 1
- 05-067-07468



Photo 3: Previous inspection weeds on berms and base of containment.

- Day-V-Ranch 34-1/2 35 1
- 05-067-07468



Photo 4: Repaired berms and base of containment.

- Day-V-Ranch 34-1/2 35 1
- 05-067-07468



Photo 5: Previous inspection tank labeling and weeds.

- Day-V-Ranch 34-1/2 35 1
- 05-067-07468



Photo 6: Corrected tank labeling and weeds.

- Day-V-Ranch 34-1/2 35 1
- 05-067-07468



Photo 7: Previous inspection waddle and sediment flow in SW corner.

- Day-V-Ranch 34-1/2 35 1
- 05-067-07468



Photo 8: Repair to SW corner.

- Day-V-Ranch 34-1/2 35 1
- 05-067-07468



Photo 9: Previous inspection wattle in SW corner.

- Day-V-Ranch 34-1/2 35 1
- 05-067-07468



Photo 10: Repaired wattle with additional straw bales.

- Day-V-Ranch 34-1/2 35 1
- 05-067-07468



Photo 11: Previous inspection waddle and sediment flow at location entrance.

- Day-V-Ranch 34-1/2 35 1
- 5-067-07468



Photo 12: Repair at location entrance.

- Day-V-Ranch 34-1/2 35 1
- 05-067-07468



Photo 113: Repairs to drainage in SW corner.

- Day-V-Ranch 34-1/2 35 1
- 05-067-07468



Photo 14: Location overview out from location entrance.