

Inspection Photos
Location Name: State of Colorado 'AA' #1
API: 05-005-06654
Inspection Date: September 7, 2017



Photo #1 – Wellhead and sign.



Photo #2 – Tank battery.

Inspection Photos
Location Name: State of Colorado 'AA' #1
API: 05-005-06654
Inspection Date: September 7, 2017



Photo #3 – Label and placard on crude oil AST.



Photo #4 – Label and placard on produced water vault.

Inspection Photos
Location Name: State of Colorado 'AA' #1
API: 05-005-06654
Inspection Date: September 7, 2017



Photo #5 – Shallow/eroded earthen berm south of produced water vault.



Photo #6 – Horizontal separator south of tank battery.

Inspection Photos
Location Name: State of Colorado 'AA' #1
API: 05-005-06654
Inspection Date: September 7, 2017



Photo #7 – Volume and NFPA label on separator need to be replaced.



Photo #8 – Gas meter shed.