

- Hugus Federal 1 05-033-06076



Photo 1: Wellhead sign.

- Hugus Federal 1 05-033-06076



Photo 2: Tank battery..

- Hugus Federal 1 05-033-06076



Photo 3: Wellhead with production tree removed. Riser painted orange.

- Hugus Federal 1 05-033-06076



Photo 4: Unmarked deadman. Painted orange by inspector.

- Hugus Federal 1 05-033-06076



Photo 5: Disconnected separator and stack in NW corner of location.

- Hugus Federal 1 05-033-06076



Photo 6: Risers where separator had been..

- Hugus Federal 1 05-033-06076



Photo 7: Location overview looking towards wellhead.

- Hugus Federal 1 05-033-06076



Photo 8: Location overview from entry point.