

- Ranger Federal #11 - 18
- 05-033-06079



Photo 1: Wellhead sign.

- Ranger Federal #11 - 18
- 05-033-06079



Photo 2: Disconnected wellhead and riser.

- Ranger Federal #11 - 18
- 05-033-06079



Photo 3: Impacted soil and gravel around base of wellhead..

- Ranger Federal #11 - 18
- 05-033-06079



Photo 4: Leak at wellhead.

- Ranger Federal #11 - 18
- 05-033-06079



Photo 5: Production tank.

- Ranger Federal #11 - 18
- 05-033-06079



Photo 6: Abandoned flowline on S side of gas meter run building.

- Ranger Federal #11 - 18
- 05-033-06079



Photo 7: Location overview looking from front of pad.

- Ranger Federal #11 - 18
- 05-033-06079



Photo 8: Location overview from back of pad.