

- Squaw Canyon - Federal 2
- 05-033-06045



Photo 1: Wellhead sign.

- Squaw Canyon - Federal 2
- 05-033-06045



Photo 2: Disconnected wellhead and riser.

- Squaw Canyon - Federal 2
- 05-033-06045



**Photo 3: Unused equipment and debris on W side of location.**

- Squaw Canyon - Federal 2
- 05-033-06045



**Photo 4: Unused equipment and debris on W side of location.**

- Squaw Canyon - Federal 2
- 05-033-06045



**Photo 5: Pipe section on W side of location.**

- Squaw Canyon - Federal 2
- 05-033-06045



**Photo 6: Sucker rod sections on W side of location.**

- Squaw Canyon - Federal 2
- 05-033-06045



**Photo 7: Impacted soil at riser by location entrance.**

- Squaw Canyon - Federal 2
- 05-033-06045



**Photo 8: Unmarked deadman painted orange by inspector.**

- Squaw Canyon - Federal 2
- 05-033-06045



**Photo 9: Unused risers at gas meter shed.**

- Squaw Canyon - Federal 2
- 05-033-06045



**Photo 10: Unused riser at separator.**

- Squaw Canyon - Federal 2
- 05-033-06045



**Photo 11: Unused risers outside produced water tank berms.**

- Squaw Canyon - Federal 2
- 05-033-06045



**Photo 12: ½" riser between produced water tanks.**

- Squaw Canyon - Federal 2
- 05-033-06045



**Photo 13: Unused risers inside oil tank battery. Impacted soil and gravel in left of frame.**

- Squaw Canyon - Federal 2
- 05-033-06045



**Photo 14: Impacted soil and gravel under valves and out from tank.**

- Squaw Canyon - Federal 2
- 05-033-06045



**Photo 15: Soil pile just out of NW corner of location.**

- Squaw Canyon - Federal 2
- 05-033-06045



**Photo 16: Location overview looking from W side towards production equipment.**