


Evelyn Payne F 2 Closure document 9-1-17



Well head sign for reference



Stained soils cleaned up around well head and clean soils put into place and disposed of in BP soil box to be remediated at IEI when soil box is full and ready for remediation.



Stained soils cleaned up around muffler and clean soils put into place and disposed of in BP soil box to be remediated at IEI when soil box is full and ready for remediation.



Tank and tank metal containment ring painted



Stained soils around pump jack cleaned up and disposed of in BP soil box to be remediated at IEI when soil box is full and ready for remediation.



Photo of bagged up stained soils to be transported to BP soil box for remediation at IEI