

Photo#1:  
View North over Location from top of Cut Slope



Photo#2:  
View to SE over Location Center



August 31, 2017

Photo#3:

A few pieces of Debris (Cable) remain on Location.

Photo#4:



August 31, 2017

Photo#5:

Pit / Depression at base of Fill slope



August 31, 2017