

Photo#1:
View North over Location Center



Photo#2:
View South over Location Center



August 31, 2017

Photo#3:

Photo#4:

Debris on Location.



August 31, 2017

Photo#5:

Cable & Anchors remain on Location.

Photo#6:



August 31, 2017

Photo#7:

Equipment Location graveled with Drains, pipes & stubs in place

Photo#8:



August 31, 2017

Photo#9:

Concrete Slab adjacent to PA Marker is
Approximately 5' X 24'.



August 31, 2017

Photo#10:

Weeds, Russian thistle, Halogeton & Cheat grass populate
The Site.

