



Photo 1: View of the project area from the northeastern corner facing center.



Photo 2: View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is progressing within the interim reclamation areas such as crested wheatgrass (*Agropyron cristatum*).



Photo 3: View of a headcut in the southeastern portion of the project area.



Photo 4: View downstream of headcut in Photo 3, approximately 4 feet wide and 5 feet deep. This needs to be stabilized.



Photo 5: View of area in the eastern portion of the project area where musk thistles appear have recently been treated.