



**Photo 1: View of the project area from the northeastern corner facing center.**



**Photo 2: View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is irrigated and largely comprised of squirreltail (*Hordeum jubatum*) and sedge species (*Carex* spp.).**



**Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward.**



**Photo 4: View of musk thistles (*Carduus nutans*) growing along the access road.**