

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/06/2017

Submitted Date:

09/14/2017

Document Number:

687900324**FIELD INSPECTION FORM**

Loc ID 333937 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Harrison, Lyndon	505-333-3100	Lyndon_Harrison@xtoenergy.com	
Trujillo, Irwin	719-846-0272/719-859-2264	irwin_trujillo@xtoenergy.com	Sr. Env. Tech., Raton Basin
Fitzgerald, Edie	719-845-2108/719-859-1394	Edie_Fitzgerald@xtoenergy.com	Env. Tech, Raton Basin

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259038	WELL	PR	01/23/2001	GW	071-07182	HILL RANCH 27-12 V	PR
259039	WELL	PR	05/30/2003	GW	071-07183	HILL RANCH 27-12 R	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected FacilitiesFacility ID: 259038 Type: WELL API Number: 071-07182 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 259039 Type: WELL API Number: 071-07183 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: 30' x 70', sharedCorrective Action: Date:

Monitoring:

Monitoring Type

Comment`

Other

Blue stake