




## Form Information


Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Sep 14, 2017 8:57:18 AM MDT
Server Receive Date:	Sep 14, 2017 8:57:25 AM MDT
Reference Number:	20170914-1866192963
Location:	Unknown Location

## Information

Name	reclamationtablet
Date	Sep 13, 2017
Optional - Type Part of the Run Number or Lateral to Filter for Next Question	Northeast
Well Name	STATE CD 1 GAS COM
API Number	50670785200
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions
Picture North to South	



Picture South to North



Picture East to West




Picture West to East



Additional photos



Additional photos



Additional photos



Completed work description

We installed 175 linear feet of erosion logs. We repaired the rock run down in the Southeast area of the pad. Five bags worth of musk thistle were removed from location.