

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/31/2017

Submitted Date:

09/11/2017

Document Number:

680102195**FIELD INSPECTION FORM**

Loc ID 315632 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 22315Name of Operator: D & D RESOURCES, INCAddress: 2835 VILLA WAY #4City: GRAND JUNCTION State: CO Zip: 81501**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ramos, Martha		martha.ramos@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231196	WELL	PA	04/17/2014	DA	103-08865	EMERALD 240	RI

General Comment:

This is a Final Reclamation Inspection prompted by Bond Release Request for PA Well API#103-08865; Spud 11/13/1981 by Diamond Back Drilling; records for Plugging and Abandonment are not on File. PA date on Scout Card is date of Inspection Doc#673501061 reporting "No Well or Marker at this Location". An Inspection 7/16/1999 reported the Well as TA.

Operator has no email contact address in system. Inspection will be mailed via USPS to physical address on File: D & D Resources C/O BURL DAILEY 2835 VILLA WAY #4, GRAND JUNCTION, CO 81501. Inspection will be mailed out Tuesday September 12, 2017.

Inspected Facilities									
Facility ID:	231196	Type:	WELL	API Number:	103-08865	Status:	PA	Insp. Status:	RI

--

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded Pass Contoured Pass Culverts removed Pass

Gravel removed Pass

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% Fail Cropland: perennial forage _____

Weeds present Pass Subsidence Pass

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: Surface conditions; disturbed area in Well GPS position indicate this Well May have been Plugged, as no other evidence of Well is visible. Previous Inspection, 4/17/14 also reported No Well or Dry Hole Marker at Well GPS Position. Subsequent Form 6 and Cement tickets are missing in Files & need to be submitted to COGCC before Final Reclamation can be Passed. Site has had no Final Reclamation installed.

Corrective Action:	There are two Corrective Actions in this Section. CA#1) Submit information needed to document Plugging of Well, contacting NW Area Engineers if advisement needed. CA#2) Perform Final Reclamation of Location per COGCC 1004 Rules by November 1, 2017.	Date	11/01/2017
Overall Final Reclamation	Fail	Well Release on Active Location	<input type="checkbox"/>
		Multi-Well Location	<input type="checkbox"/>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401400345	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4248787
680102207	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4248784