

Inspection Photos
Location Name: Perry #1
API: 05-123-09423



Photo 1: Location, looking SW



Photo 2: Wellhead looking SE

Inspection Photos
Location Name: Perry #1
API: 05-123-09423



Photo from prior inspection for comparison



Photo 3: Unused equipment at NW corner of battery

Inspection Photos
Location Name: Perry #1
API: 05-123-09423



Photo 4: Unused riser in battery. Berm is not properly engineered in floodplain. Tanks are not properly anchored in floodplain.




Photo 5: No emergency contact number at wellhead sign.

Inspection Photos
Location Name: Perry #1
API: 05-123-09423



Photo 6: Separator improperly anchored.