

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2017

Submitted Date:

09/14/2017

Document Number:

690300052**FIELD INSPECTION FORM**
 Loc ID 335205 Inspector Name: Spencer, Stan On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 66571Name of Operator: OXY USA WTP LPAddress: P O BOX 27757 #110City: HOUSTON State: TX Zip: 77227-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Bankert, Wayne	(970) 683-5419	cogccnotifications@laramie-energy.com	<a href="#">All inspections</a>
Lujan, Carlos		carlos.lujan@state.co.us	

**General Comment:**

**Environmental****Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 5

Comment: Inspection of Spill #401399579. Spill consisted of ~5bbl of pw from subsurface dump line between separator and 300bbl PW/cond AST. AST is within poly-lined steel SPCC. Line has been excavated and exposed. Excavated soils are stockpiled within poly-lined dirt berms near south end of pad. No petroleum contamination observed within excavation such as staining, odor or sheen on small pools of rainwater.

Corrective Action: Per F-19 COA, continue to assess nature and extent of contamination with excavation and or borings and confirmation soil samples. Remediate to Table 910-1 standards and provide documentation in another Supplemental F-19 if the next phase attains Table 910-1 compliance. If not submit an F-27 with detailed assessment and remediation plan. If landfarming contaminated soil is required it must also be approved by surfaceowner. Closure data must include a figure showing spill area with sample locations plus laboratory results

Date: 10/27/2017

Reportable: YES

GPS: Lat Long

Proximity to Surface Water: 400

Depth to Ground Water:

**Water Well Complaint:**

Lat Long

DWR Receipt Num: Owner Name: GPS :

**Field Parameters:**

Sample Location: Comment:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
401403667	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4251503">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4251503</a>
690300055	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4251502">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4251502</a>