

- McCulloch #1
- 05-067-06439



Photo 1: Wellhead sign. Previous inspection.

- McCulloch #1
- 05-067-06439



Photo 2: Wellhead sign.

- McCullogh #1
- 05-067-06439



**Photo 3: Erosion channel cut into cut slope. Previous inspection.**

- McCullogh #1
- 05-067-06439



**Photo 4: Erosion channel cut into cut slope.**

- McCullogh #1
- 05-067-06439



**Photo 5: Erosion channel on perimeter at top of fill slope.  
Previous inspection.**

- McCullogh #1
- 05-067-06439



**Photo 6: Erosion channel on perimeter at top of fill slope.**



- McCullogh #1
- 05-067-06439



**Photo 7: Additional erosion channels in cut slope.**

- McCullogh #1
- 05-067-06439



**Photo 8: Additional erosion channel in fill slope.**

- McCullogh #1
- 05-067-06439



**Photo 9: Rolled up fencing beside gas meter shed.**

- McCullogh #1
- 05-067-06439



**Photo 10: Wider view of erosion channel in cut slope behind tank battery.**