



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Sep 21, 2017 3:29:11 PM MDT
Server Receive Date:	Sep 21, 2017 3:29:19 PM MDT
Reference Number:	20170921-1866589124
Location:	101-1079 S Skylane Dr, Durango, CO 81303, USA Sep 21, 2017 3:28:47 PM MDT [ <a href="#">View Map</a> ]

## Information

Name	reclamationtablet
Date	Sep 21, 2017
Location Name (Other)	Lucero 2
Location API (Other)	06708826
Select State	Colorado
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Completed work description

mowed weeds on the Lucero 2