

Inspection Photos

9/18/2017

Operator: PETRO-CANADA RESOURCES (USA)
INC - 72085

Location ID: 311680

Inspection Doc. Number: 682502571
Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311680



Photo 1: Photo taken from pad location, facing southwest. Photo shows the cut slope of the location remains unreclaimed.



Photo 2: Photo taken from the east end of the pad location. Photo shows erosion degradation due to stormwater runoff. These areas need to be reclaimed.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311680



Photo 3: Photo taken from the east end of the pad location. Photo shows trash debris.



Photo 4: Photo taken from the east end of the pad location, facing northwest. Photo shows erosion degradation due to stormwater runoff. These areas need to be reclaimed.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311680



Photo 5: Photo taken from the access road. Photo shows areas of the access road where ruts remain and erosion degradation has occurred. These areas will need to be reclaimed.



Photo 6: Photo taken from the access road. Photo shows areas of the access road where ruts remain and erosion degradation has occurred. These areas will need to be reclaimed.



Photo 7: Photo taken from the access road. Photo shows areas of the access road where ruts remain and erosion degradation have occurred. These areas will need to be reclaimed.