

Inspection Photos

9/18/2017

Operator: PETRO-CANADA RESOURCES (USA)
INC - 72085

Location ID: 311698

Inspection Doc. Number: 682502575
Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from within the drainage. These areas require reclamation.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311698



Photo 2: Photo taken to the south of the location, facing east.
Photo shows access roads. Access roads will require reclamation.



Photo 3: Photo taken to the south of the location, facing east.
Photo shows access roads. Access roads will require reclamation.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311698



Photo 4: Photo taken to the south of the location, facing west. Photo shows access roads. Access roads will require reclamation.



Photo 5: Photo taken to the southwest of the location, facing west. Photo shows access roads. Access roads will require reclamation.