

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Sep 22, 2017 8:09:11 AM MDT
Server Receive Date:	Sep 22, 2017 8:09:16 AM MDT
Reference Number:	20170922-1866613268
Location:	101-1079 S Skylane Dr, Durango, CO 81303, USA Sep 22, 2017 8:09:02 AM MDT [View Map]

Information

Name	reclamationtablet
Date	Sep 21, 2017
Location Name (Other)	Ute ac 2
Location API (Other)	06708812
Select State	Colorado
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Completed work description

mowed weeds on right of way and around pad