

Inspection Photos
Location Name: Island Butte 2 #8
API: 05-083-06538



Island Butte 2 #8 line heater.



Island Butte 2 #8 location berm.

Inspection Photos
Location Name: Island Butte 2 #8
API: 05-083-06538



Island Butte 2 #8 pump jack.



Unused chemical injection system.

Inspection Photos
Location Name: Island Butte 2 #8
API: 05-083-06538



400 bbl. AST.



Location berm along west side of location.