


Photo#1:

Overview of Location from Entry, looking North East.



September 13, 2017

Photo#2:

Fill Slope vegetation establishing in some areas .



Photo#3:

Weeds & Bare ground prevalent in other sections



September 13, 2017

Photo#4:
Thistle at base of Fill Slope



Photo#5:
Halogeton on Pad



September 13, 2017

Photo#6:

Access Road is weed infested .



September 13, 2017

Photo#7:

Desirable Vegetation is struggling to establish on Cut Slope. .



September 13, 2017