

Inspection Photos

9/25/2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP
- 47120

Location ID: 327317

Inspection Doc. Number: 682502605
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the west end of the location, facing south. Photo shows pipe riser equipment has been removed per CA's

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120
Location ID: 327317



Photo 2: Photo taken from the northwest end of the location, facing west. Photo shows access road has not been reclaimed per COGCC 1000 series reclamation rules and requirements. Corrective actions have not been addressed.



Photo 3: Photo taken from the access road entrance, west of the location. Photo cattle guard and gate remains; access road has not been reclaimed per COGCC 1000 series reclamation rules and requirements. Corrective actions have not been addressed.